


CORBY AVENUE


LEGEND

- ▲ **B-1** Soil Boring (Mar-May 90)
- **P-1** Soil Boring (Oct 97)
- ⊙ Monitoring Well (Mar-May 90)
- ⊙ Monitoring Well (Jul 00)
- (190/290/ND/ND) Concentrations of TPHg/TPHd/MTBE/Benzene in Groundwater in µg/l:
Reporting Limits = (50 / 50 / 0.5 / 0.05) µg/l
- NS; ND Not Sampled; Not Detected above Reporting Limits

0 30
feet
(Scale Approximate)



Property Line



MW-5
(640/170/1.4/88)
⊙
● **P-2**

Relocated Gas/Com Line

Extent of Over-excavation

Smoking/
Break Shed

Concrete Slab

Fence

DEALERSHIP
BUILDING

● **P-1**

▲ **B-1**

▲ **B-7**

⊙ **MW-1**
(Destroyed)

▲ **B-2**

● **P-3**

⊙ **MW-6**
(190/290/ND/ND)

Former Gasoline
UST Location

▲ **B-3**
Former Diesel
UST Location

Truck
Route

● **P-4**

⊙ **MW-3**
(Destroyed)

⊙ **MW-4**
(NS)

▲ **B-4**

▲ **B-5**

⊙ **MW-2**
(NS)

▲ **B-6**

Former Waste Oil
UST Location

Reference: Plate 2 based on Touchstone Development's
07/97 Plate 2, Boring and Monitoring Well Locations

EDD CLARK & ASSOCIATES, INC.
ENVIRONMENTAL CONSULTANTS

SITE MAP,
23 July 2002 Groundwater Analyses
2800 Corby Avenue
Santa Rosa, California

PLATE

2

JOB NUMBER	0307,001.97	REVIEWED BY	EC&A, John Calomiris	DATE	August 1998	REVISED	September 2002	SHEET NO.	1 of 1
------------	-------------	-------------	----------------------	------	-------------	---------	----------------	-----------	--------

(TRACE#311/RG/16Sep02)